

# Rescue from a Permit Required Confined Space

Jim Ciandella NW Regional Sales Manager, FallTech





## Considerations

- Confined spaces vary in size, shape and configuration
- Hazards
  - entanglement, electric arc, engulfment, and general lift obstructions





### **General Rescue Requirements**

- Non-entry rescue required
  Unless retrieval equipment :
  - Increases the overall risk
  - Would not contribute to the rescue of the worker





## **Rescue Requirements**

- If non-entry rescue is not feasible a rescue plan must be in place
  - Specific hazards
  - Training on rescue methods
  - Equipment





### System Configurations for Non-Entry Rescue Methods


- Vertical type permit spaces more than 5 feet
  Mechanical devices required
- Considerations
  - Means of entry/egress
  - Mitigation of fall hazards
  - Method of emergency retrieval





### Single Line - Winch Only Entry/Egress Using Ladder

- Keep the winch line taut to avoid any potential overload due to a fall event on the winch line
- Winch is for emergency retrieval only
  - Not a fall arrest device








### Single Line - SRL-R Only Entry/Egress using ladder

- Cable will pay freely in and out
- SRL-R will arrest the fall
  - Reduce fall forces applied to the body
- Backup emergency retrieval winch for rescue
- Not to be used for ordinary entry/egress








### Dual Line - Winch & SRL/Alternate PFAS Entry/Egress Using Ladder

- Personal Fall Arrest System (PFAS)
  - SRD or
  - Fall Arrestor Connector Subsystem (FACSS)
- Winch
  - Emergency retrieval device






### Dual Line – Winch and SRL-R Entry/Egress Using a Winch

- Winch line
  - Attaches to shoulder yoke or sternal D-Ring
    - Suspends, raises and lowers
- Backup system required
  - SRL-R
    - Attaches to dorsal D-ring for fall arrest and emergency retrieval





























#### **Proper Preparation Important....**



- Unsafe Tripod Setup
- Attendant?
- Ventilation?







### **Open Q&A**





# Thank you for Joining us Today

#### Jim Ciandella

NW Regional Sales Manager, FallTech Office: 800-719-4619 Cell: 310-502-8159 jciandella@falltech.com